

- NOTES:**
- GRID REFERENCE GRID BY DETAIL TO OS DATA.
 - LOCATIONS OF ALL STRUCTURAL DEFECTS AND MANHOLE MARKERS LOCATED ON THIS DRAWING CORRESPOND TO THE GRID REFERENCE SYSTEM.
 - DRAINAGE INFORMATION HAS BEEN OBTAINED BY SURFACE INSPECTION ONLY AND SHOULD BE CROSS CHECKED IN CENTRAL AREAS.
 - REF. TO BE READ IN CONJUNCTION WITH INSPECTOR'S SURVEY REPORT.

Key:

- COMBINED WATER SEWER WITH SIZE
- CONNECTION TO BACK DRIP
- MANHOLE REF. NO. AND DESCRIPTION
- MANHOLE CHAMBERS
- SEWER DEFECT CHANGE AND DESCRIPTION



mksurveys
www.mksurveys.co.uk
141 GERRARD STREET
LEEDS LS2 7PQ
0113 276 0000
0113 276 0001
0113 276 0002

INSURER SURVEYS
CONTRACTOR FOR INSURER SURVEYS
141 GERRARD STREET
LEEDS LS2 7PQ
0113 276 0000
0113 276 0001
0113 276 0002

SAMPLE

Drainage Survey (With structural defects)

Scale	1:1200	Sheet Size	A1	Date	-
Project Number	Sample	Surveyed By	-	Approved By	-

